

Mysurvey : Changelog

03/08/2026

FEA : New feature | IMP: Improvement | BUG: hotfix

#	Type	Contexte EN	Description EN
#####			
03/08/2026 Version 1.8.9.8			
FEA	Rules		Activation of the functionality for the use and display of attribute data in all license types (including Standard and SMART) (import rules system)
IMP	Import		Update of the external format import library that solves problems in the import of IFC files
IMP	DAC		Externalization of the search distance parameter for GC elements to allow the detection of elements within 10cm of the wall
BUG	Manager		E57 file conversion works with MySurvey_import again
BUG	Manager		The creation of virtual stations (single or batch) works again (POC menu)
22/05/2026 Version 1.8.9.6			
BUG	Application		Fixed the behaviour of the tooltip when hovering over an item in a view
19/05/2026 Version 1.8.9.5			
FEA	DAC		Exporting the LDIR value for both sides of a FireDamper in IFC
BUG	Objects		The loading of CAD objects and models has been fixed in "non-project" mode
BUG	View2D		Fixed an issue causing abnormal CPU usage when UHD is open in a view
27/04/2026 Version 1.8.9.4			
BUG	Application		NodeLocked licenses no longer deactivate when MySurvey is closed and work without internet for a predetermined period of time per license
BUG	Application		Fixed the notification including a progress bar, especially when optimizing the location of objects
BUG	Application		The "MapName" property is correctly interpreted on older projects
24/04/2026 Version 1.8.9.3			
FEA	DAC		Export the LDIR value of both sides of a FireDamper to the Excel cell corresponding to the LDIR asbuilt
FEA	Objects		Cones created according to a model (Monophasic or Diphasic) are now considered as "static" geometry, thus preventing the modification of their intrinsic geometry. However, it is always possible to move them or change their orientation. In addition, the cone(s) are grouped together in a compacted group when they are created
BUG	Manager		Low-resolution images (Dezoom) are correctly generated
BUG	Manager		LOC files contain the necessary properties for SMART (PRODUCER_NAME, IMAGE DIRECTORY,SUFFIX GREY,SUFFIX COLOR,SUFFIX MASK,SUFFIX DEZOOM)
BUG	Manager		the "MapName" property is indeed registered in the SiteStructure.xml file
06/03/2026 Version 1.8.9.2			
IMP	Application		CryptLex license libraries update
BUG	Application		Fix enabling MySurvey to launch when Java Access Bridge is enabled on the user's computer
13/02/2026 Version 1.8.9.1			
FEA	Application		Use of the OpenJDK 25 engine (instead of version 19), with gains in terms of stability (solves occasional crashes when detecting pipes or planes in version 1.8.8.12)
FEA	DAC		[DAC] Restore Slope U criteria for DOOR FRAMES (in DAC module, Excel export , IFC export)
IMP	DAC		Decrease the size of the images generated for DOORS objects (reduces display times)
IMP	DAC		Disable the "coloring of selected objects" mode in the display of these objects in the DAC module
IMP	View2D		Interact with the 3D view angular sector on the 2D plane to move the 3D view camera
IMP	Rules		Use an "endwith" operator to filter attributes in the rule system
IMP	Rules		Allow an attribute to be defined based on part of its name
BUG	Application		Disable point cloud-dependent creation tools
BUG	Application		Clean the build to remove libraries that are not needed for the SMART version.
BUG	Import		A folder specified as "Autoload" and containing no files no longer causes an empty folder to appear in the MySurvey tree
15/01/2026 Version 1.8.8.12			
FEA	Objects		Hyperpath attributes can be set in the rule file, allowing a clickable link to be displayed in the tooltip when hovering over the object or in its properties window.
FEA	Stations		The maximum size of the badges can be set in the configuration file "graphical.conf" through the parameter "MAX_STATION_SIZE_2D". The default value of 250cm can be increased to allow the user more amplitude to adjust the size of the pads on the plane. This is useful when the plans represent a large area, such as for site exteriors.
FEA	Application		All references to SWITCH are replaced by "SMART"
IMP	Tree browser		The context menu used on the IMPORT node or the imported files nodes now displays the "delete" option to remove the imported files from the current session.
IMP	Annotations		It is now possible to "drag and drop" a video file (MP4 formats) from Windows Explorer into one of the MySurvey views in order to automatically create a "Photoitem" object.
IMP	DAC		The coloring of the selected objects is adapted to the "DAC" objects so as not to color the shape already bearing the green or red compliance color
IMP	Search		Deleting a large number of objects from the search engine results is now faster
BUG	Manager		Fix impacting project loading and virtual station creation
BUG	Application		The time it took to launch the application via the network (Mysurvey_network) was abnormally long (reading annotation icons on the network)
03/12/2025 Version 1.8.8.9			
FEA	Objects		Choosing the transparency value of objects is now available from the object property window
FEA	Objects		The MySurvey application administrator can now define the execution of an action following the creation of an annotation in order to invite the user to name the object that has just been created, thanks to the display of a dialog.
FEA	Search		It is possible to select all the search engine results by using the "CTRL+A" key combination when the window has the focus

FEA	Objects	When deleting items that are locked, it now gives the ability to delete all locked items, leaving the ability to delete a treescene while keeping the items locked.
FEA	Manager	The name of a floor can be edited even in a project that has already been published
IMP	Tree browser	Complying and uncompacting a large tree is now faster
IMP	Corbeille	Removed the small 'trash' button from the title bar of the groups tab
BUG	Manager	The generation of the index.html file is now correctly encoded and smarter, based on the project information
BUG	Manager	The locators.csv file is better read/written, takes into account the status correctly and adds missing fields
BUG	Manager	Confirmation is requested as to whether the plane setting should be kept when the background is changed
BUG	Manager	The generation of the low-resolution version of the image of a floor is correctly performed
BUG	Tree browser	When the application starts, the root node of the project in the SITE tab is unfolded so that the list of floors is directly visible
05/11/2025		Version 1.8.8.7
FEA	Manager	Enable the positioning of UHD and POI photo stations (points of interest) by stitching the location on the map
FEA	Manager	Ability to account for clip registration while maintaining the relative positions of manually placed UHD photos
FEA	Manager	The SIOC generator tool now allows the creation of a combined point cloud of several E57 files from mobile scans as well as locators from fixed stations
FEA	Application	Preferences for setting mouse and keyboard behaviors for navigating views can be set in behavior model files to mimic the behavior of other software. A list of existing templates is available in the user preferences window
FEA	Application	Two new options in the system menu allow users to save and reload user's settings. These preferences apply not only to general settings that are common to all projects, but also to settings that are specific to the current project, such as icon sizes. When the settings load, they are applied immediately, without the need to relaunch the application.
FEA	Application	When MySurvey is used in "no-project" mode, the settings are now preserved when the application is closed and will be automatically applied the next time you open it in this mode.
FEA	Application	When MySurvey is used in "no-project" mode, the data created by the user is not kept when the application is closed; In this case, a warning will be presented to them when the application is closed, inviting them to save their work.
FEA	Subscriptions	The user can now set favorite deal numbers, in order to filter the available publications. These preferences are persistent between two MySurvey sessions for the same project.
IMP	3D Engine	Improved the display performance of CAD models and the relevance of the objects displayed. The parameters can be set by the user in the display preferences by selecting between 3 predefined modes or more finely by playing with the values of the number of triangles and the size of objects to be displayed in the 3D view
IMP	Application	The tooltip that is displayed when hovering over objects is timed out so that it only appears after 1 second if the mouse remains stationary on the object, and slightly offset from the mouse, thus improving navigation in the 3D view.
IMP	Tree browser	The management of the position in the object tree has been improved, avoiding losing focus on the tree currently present on the screen: when deleting objects, moving in groups or simply activating a group, the position in the tree is no longer changed.
IMP	Multi-sélection	Using the "DELETE" key on a multi-selection correctly deletes the selected elements, and the permanent deletion of a multi-item requires confirmation only once (and no longer for each object)
BUG	Import	Fixed the reading of object colors when importing an IFC file
BUG	Objects	The extrusion of a rectangular surface does indeed generate a "box" object whose dimensions are modifiable and no longer an extruded polygon that does not allow its structural modification
BUG	Manager	Adjusted POI import from Navisworks (coordinate system)
BUG	Manager	It is again possible to generate "virtual" stations with the Manager
BUG	Tree browser	Fixed the bug that allowed an item to be created in a locked group. This occurs when creating an object that involves selecting another object, such as creating a truncated cone by selecting an existing cylinder because the created object was placed in the same group as the source object, even though the source object was locked. From now on, created objects are always created in the active group.
BUG	Search	The "locate in tree" function works again if used from the search engine
BUG	Objects	The Annotation Create button on the main toolbar is grayed out when creating an object
BUG	Subscriptions	Fixed sharing a group with forbidden characters in a file name by "cleansing" the file name before publishing
Bug	Objects	Selecting a "POI" object no longer turns the mouse cursor into a green arrow, wrongly signifying a change of point of view