

MySurvey Keyboard shortcuts

Application

Keyboard shortcut	Action
A	Display params settings
[Alt]	Hide stations (keep pressed)
B	Display / hide side panel
[Ctrl] B	Quick navigation mode
[Ctrl] [F5]	Display shared data
[F5]	Update shared data
O	Reorganise workspace
S	Displays my shared data

Tools

Keyboard shortcut	Action
L	(Keep pressed) Synchronize the second view with the mouse on the first view
D	Display / hide laser
[Esc]	Cancel current action
[Space]	Load the last used tool
[Insert]	Insert a vertex on a polyline
[Del]	Delete the selected object or vertex
M	Activate the magnetism
X	Lock X axis
Y	Lock Y axis
Z	Lock Z axis

Map view

Keyboard shortcut	Action
/	Reset map position

Panoramic view

Keyboard shortcut	Action
[Backspace]	Go back to previous station
[Shift] [Backspace]	Go to next station
[Ctrl] -	Reduce luminosity
[Ctrl] +	Increase luminosity
[Ctrl] 0	Reset panoramic's luminosity
H	Open UHD view
C	Toggle Color / Intensity
P	Toggle no point view
R	Toggle rendering mode
T	Toggle transparent / full render

3D view

Keyboard shortcut	Action
1	Change rotation type
[F1]	Front view
[F2]	Side view
[F3]	Top view
[F4]	Perspective / orthographic view
[Home]	Extended zoom
/	Extended zoom